

LOCATION: BLM-22-570

HYDRAULIC CONDITIONS: Apparent Confined, Fractured (Flow-Banded Rhyolite) Aquifer

PERTINENT OBSERVATION: Drilled 0'-340', blew hole dry, let recover overnight and detected no water. Drilled 340'-500', blew hole dry, let recover overnight and detected no water. Drilled 500'-585', drilled into possible water-bearing unit near bottom, blew hole dry. Let recover overnight and measured water level at 523.77'. Water level had risen to 506.51' when measured the next day.