

LOCATION: BLM-32

HYDRAULIC CONDITIONS: Inconclusive-fractured rhyolite aquifer.

PERTINENT OBSERVATIONS:

No observations of formation water production were recorded in field log book. Rhyolite bedrock was encountered at 372'. Borehole TD was 750' and water level measured by geophysical logging was 518'.