

* NOTE: TOTAL LENGTH OF COMPLETION PIPE DOES NOT CORRELATE WITH MEASURED DEPTH OF WELL. TALLY OF PVC PIPE IS PROBABLY IN ERROR AND SHOULD BE 163.7'.

MONITOR WELL BLM-3-182 COMPLETION DIAGRAM