Pressure Profile Report

Well ID **WW-2** **Profile Date** **4/30/99**

Well Description: 1.5" Multi-port

Brass Cap Elev. (ft) 0.00 Probe Serial #:

Inner Casing Elev. (ft) 0.00 Description: MOSDAX

Stickup (ft) 0.00

	Initial Conditions	Final Conditions
Atmospheric Pressure (psi)	12.67	12.64
Temperature (°C)	20.77	22.85
Depth to Water (m)	116.32	116.42

Port Num	Port Depth	Port Type	Pressure (psi) Casing	Pressure (psi) Formation	Temperature (°C Casing	Temperature (°C Formation	Depth to Water (m)	Depth to Water (ft)	Piez Level (m)	Piez Level (ft)	Piez Elev. (ft)
1	975	Press	273.09	275.73	29.02	28.71	115.19	377.94	-113.33	-371.85	-371.85
2	960	Samp	266.69	268.70	30.69	30.69	115.21	378.00	-113.80	-373.37	-373.37
3	860	Press	223.27	228.65	29.93	30.02	115.34	378.43	-111.56	-366.02	-366.02
4	845	Samp	216.76	218.93	29.47	29.51	115.37	378.53	-113.84	-373.52	-373.52
5	685	Press	147.27	148.37	27.75	27.84	115.60	379.28	-114.83	-376.75	-376.75
6	670	Samp	140.72	143.11	27.32	27.38	115.62	379.35	-113.94	-373.84	-373.84
7	510	Press	71.10	73.83	25.54	25.66	115.84	380.07	-113.92	-373.77	-373.77
8	495	Samp	64.56	67.35	25.09	25.13	115.86	380.14	-113.90	-373.70	-373.70
9	330	Press	12.84	12.85	23.88	23.93	-1.00	330.00	-100.57	-329.98	-329.98
10	170	Press	12.76	12.76	23.36	23.42	-1.00	170.00	-51.81	-170.00	-170.00

All samp ports 2 (=)

Comments:

NOTES: Piez Level (ft) = Depth to Water (ft) - ((Formation Press - Casing Press) / 0.4335) - Stickup

Piez Elev (ft) = Brass Cap Elev. (ft) + Piez Level (ft)

If the water level is below the port, then substitute the Port Depth in the equation.