

LOCATION: 100-B-\*

HYDRAULIC CONDITIONS: Inconclusive

PERTINENT OBSERVATIONS: No water observed while drilling, 0' to 401'. After 7 days of recovery, static water level stabilized at **308.0'**.