

LOCATION: 200-B-240

HYDRAULIC CONDITIONS: Apparent Water table

PERTINENT OBSERVATIONS: No water was detected in borehole after overnight recovery at 165'. Water was first detected by driller at 183' but the producing zone was very weak. Water level in borehole rose to 181' when borehole was 230' deep. At 248' a large fracture was encountered. This fracture produced significantly more water than any other zone.