

LOCATION: BLM-13-300

HYDRAULIC CONDITIONS: Apparent Artesian

PERTINENT OBSERVATIONS:

Drilled to 241'. Let recover overnight. No water detected. First signs of water at 281'. Static stabilized at 237.3'.