

LOCATION: BLM-2-630

HYDRAULIC CONDITIONS: Apparent Water table

PERTINENT OBSERVATIONS:

Water first detected between 460' and 500'. The thinning of the drilling fluid was the determinant observation. This thinning was gradual at first then increased with depth. Close to T.D. (~ 600') exceptionally great amounts of water were blown from hole.